

Warranty of Avery Dennison® Films

Instructional Bulletin #1.30 (Revision 9)

Dated: 06/09/20

1.0 Scope


This instructional bulletin describes the conditions and circumstances that would impact the warranty on Avery Dennison's film. See the applicable product data sheet for specific warranty information.

2.0 Reduction of Warranty Expectations

In the event of exposure in desert situations, or within areas considered high UV exposure, the warranty will be reduced from the information provided in the appropriate Product Data Bulletins, and Instructional Bulletins. Based on the Zone Chart (shown on page 2) Warranty in regions located in Zone 1 will perform in vertical applications as specified in the Product Data Bulletin. Materials used in regions identified in Zone 2 will have a reduction of the specified warranty length by 20%, and those used in Zone 3 regions will have a 60% reduction in warranty length. In the event the product is exposed to multiple zones the warranty will be reduced based on the largest reduction.

The warranty will be reduced if the product is exposed other than vertical. The definition of vertical exposure is $\pm 10^\circ$ of vertical; a non-vertical exposure in an application is where a film is applied to a surface that is $10\text{-}45^\circ$ from vertical. The reduction of warranty for non-vertical applications is 20% less than the published vertical warranty for a specific product.

If a product is applied non-vertically and is exposed to Zone 2 or 3, the warranty will be reduced by the sum of the applicable zone and orientation reductions. For example, a non-vertical product in zone 2 is reduced by 40% (20% reduction for non vertical + 20% reduction for zone 2).



Section 1 – General Information

Instructional Bulletin

Page 1 of 7



Graphics
Solutions

www.graphics.averydennison.com
Customer Service: 800-282-8379

3.0 Horizontal Applications

Unless otherwise specified in the individual product data sheet, horizontal applications are not warranted and do not have any expectations of warranty.

4.0 Zones

4.1 Zone 1

- Austria
 - Belarus
 - Belgium
 - Bosnia & Herzegovina
 - Canada
 - Denmark
 - Ecuador
 - Estonia
 - Finland
 - France
 - Georgia
 - Germany
 - Hungary
 - Iceland
 - Italy
 - Latvia
 - Liechtenstein
 - Lithuania
 - Luxembourg
 - Macedonia
 - Monaco
 - Netherlands, the
 - Norway
 - Poland
 - Romania
 - Russia
 - Slovakia
 - Slovenia
 - Sweden
 - Switzerland
 - Tasmania
 - Ukraine
 - United Kingdom
 - **United States of America***
 - Uzbekistan
 - Vatican City
 - Yugoslavia
- *except areas noted as zone 2 and 3

4.2 Zone 2

- Afghanistan
- Albania
- Andorra
- Argentina
- Armenia
- Australia under the line Perth/Brisbane
- Azerbaijan
- Bahamas
- Bangladesh
- Barbados
- Belize
- Bhutan
- Bolivia
- Brazil
- Burkina Faso
- Burundi
- **California** (see map)
- Cambodia
- Cameroon
- Cape Verde
- Caribbean Isles
- Chile
- China
- Colombia
- **Colorado** (see map)
- Costa Rica
- Cyprus
- Dominica
- Dominican Republic
- East Timor
- El Salvador
- Fiji
- Greece
- Grenada
- Guatemala
- Guyana
- Haiti
- Honduras
- India
- Indonesia
- Ivory Coast
- Jamaica
- Japan
- Kazakhstan
- Korea (South)
- Kyrgyzstan
- Laos
- Lesotho
- Madagascar
- Malaysia
- Maldives
- Malta
- Mauritius
- Micronesia
- Moldova
- Myanmar (Burma)
- Nepal
- *New Zealand*
- **Nevada** (see map)
- Nicaragua
- Pakistan
- Panama
- Papua New Guinea
- Paraguay
- Peru
- Philippines
- Portugal
- **Puerto Rico**
- Rwanda
- Samoa
- San Marino
- Sao Tome & Principe
- Singapore
- South Africa (East)
- Southwest Texas
- Spain
- Sri Lanka
- Suriname
- Swaziland
- Taiwan
- **Texas** (see map)
- Thailand
- Togo
- Trinidad & Tobago
- Turkey
- Turkmenistan
- Ukraine
- Uruguay
- **Utah** (see map)
- Venezuela
- Vietnam

Section 1 – General Information Instructional Bulletin

Page 2 of 7



Graphics
Solutions


www.graphics.averydennison.com
Customer Service: 800-282-8379

4.1 Zone 3

- Algeria
- Angola
- Australia above line Perth/Brisbane
- **Arizona**
- Bahrain
- Botswana
- **California** (see map)
- Central African Rep.
- Chad
- **Colorado** (see map)
- Congo
- Egypt
- Equatorial Guinea
- Eritrea
- Ethiopia
- Gabon Gambia
- Ghana
- Guinea
- Guinea-Bissau
- **Hawaii**
- Iraq
- Israel
- Jordan
- Kenya
- Kuwait
- Lebanon
- Liberia
- Libya
- Mali
- Mauritania
- Mexico
- Morocco
- Mozambique
- Namibia
- **Nevada** (see map)
- **New Mexico**
- Niger
- Nigeria
- Oman
- Qatar
- Saudi Arabia
- Senegal
- Sierra Leone
- Somalia
- South Africa (West)
- Tanzania
- Tunisia
- **Texas** (see map)
- Uganda
- **Utah** (see map)
- United Arab Emirates
- Yemen
- Zambia
- Zimbabwe

5.0 North America

5.1 United States Coverage Map by Zone



Section 1 – General Information Instructional Bulletin


5.1 Zone Reductions

- Zone 1 areas are indicated in green and include the United States and Canada unless otherwise noted on the map above.
- Zone 2 areas are indicated in yellow and will have a 20% warranty reduction.
- Zone 3 areas are indicated in red and will have a 60% warranty reduction.
- Areas indicated in white are referenced in individual maps below


Texas




Utah



Nevada




Colorado



Section 1 – General Information Instructional Bulletin

California



Section 1 – General Information Instructional Bulletin

Page 5 of 7




Graphics
Solutions

www.graphics.averydennison.com
Customer Service: 800-282-8379

6.0 Australia Coverage



7.0 South Africa



Section 1 – General Information Instructional Bulletin

Page 6 of 7



Graphics
Solutions

www.graphics.averydennison.com
Customer Service: 800-282-8379

Questions regarding the warranty of a specific product should be directed to your Avery Dennison sales, marketing or technical representative. Additional information can also be obtained by contacting the Customer Service at 800-282-8379, or visit the Avery Dennison webpage www.graphics.averydennison.com.

Revisions have been italicized.

Avery Dennison™ is a registered trademark of Avery Dennison Corporation

Section 1 – General Information
Instructional Bulletin

Page 7 of 7



Graphics
Solutions

www.graphics.averydennison.com
Customer Service: 800-282-8379